

Aroseptic Pulvis Antisepticus failed to bear the common or usual name of each active ingredient; 502 (f) (1)—the labeling of the *Aroseptic* failed to bear adequate directions for use as a douche, and the labeling of *Petty's toothache drops* bore no directions for use; 502 (f) (2)—the labeling of *Petty's pile ointment*, *Petty's Heal-Aid ointment*, and *Petty's Aroseptic Pulvis Antisepticus* failed to bear adequate warnings against use in bleeding piles, and the labeling of *Petty's toothache drops* failed to warn that the article was only for temporary use until a dentist could be consulted.

DISPOSITION: 8-2-55. Default—destruction.

DRUG AND DEVICE ACTIONABLE BECAUSE OF CONTAMINATION WITH FILTH

4991. Dried stillingia root. (F. D. C. No. 39120. S. No. 2-128 M.)

QUANTITY: 14 50-lb bags at Marion, Va., in possession of R. T. Greer & Co.

SHIPPED: Between 4-12-55 and 7-12-55, from Fort Myers, Fla.

LBELED: 4-30-56, W. Dist. Va.

CHARGE: 501 (a) (1)—contained rodent hairs and rodent urine; and 501 (a) (2)—held under insanitary conditions.

DISPOSITION: 6-14-56. Default—destruction.

4992. Rubber prophylactics. (F. D. C. No. 38713. S. No. 40-504 M.)

QUANTITY: 1,008 *rubber prophylactics* at St. Paul, Minn.

SHIPPED: 8-4-55 and 9-7-55, from North Kansas City, Mo., by Dean Rubber Mfg. Co.

LABEL IN PART: (Carton containing 3 prophylactics) "Peacocks Redi-Wet Rubbers In Foil * * * Hygienically Lubricated * * * These Redi-Wet Peacock Rubbers are hygienically Pre-Lubricated with proven exclusive formula."

RESULTS OF INVESTIGATION: Examination showed that the article consisted of rolled rubber prophylactics packaged individually in hermetically sealed metal foil containers. Each *rubber prophylactic* was moistened with a small amount of viscous liquid, intended to act as a lubricant during coitus. This liquid coating on the individual prophylactics was contaminated with an extensive and obvious mold growth.

LBELED: 11-23-55, Dist. Minn.

CHARGE: 501 (a) (1)—contained, when shipped, a decomposed substance by reason of contamination with mold; 501 (c)—the purity and quality of the article fell below that which it purported and was represented to possess since the lubricant liquid used to coat the individual *rubber prophylactics* was contaminated with an extensive mold growth; and 502 (a)—the label statement "Hygienically Lubricated" was false and misleading as applied to a product contaminated with extensive mold growth.

DISPOSITION: 1-5-56. Default—destruction.

DRUGS ACTIONABLE BECAUSE OF DEVIATION FROM OFFICIAL OR OWN STANDARDS*

4993. Elixir of terpin hydrate and codeine (2 seizure actions). (F. D. C. No. 38651. S. Nos. 23-837 M, 23-851 M.)

QUANTITY: 240 2-oz. btls. at Phoenix, Ariz.

*See also Nos. 4986, 4992.